



# Federal Aviation Administration

## Memorandum

Date: July 30, 2009 Refer to: L115W-09-665

To: ACE-7; Docket No. FAA-2007-28434; Directorate Identifier 2007-CE-053-AD; Amendment 39-15580; AD 2008-13-17

From: Robert P. Busto, Acting Associate ACO Manager, Wichita ACO, *Jon A. Busto*  
Electrical Systems and Avionics, ACE-119W

Prepared by: Jose R. Flores, ACE-119W, 316-946-4133

Subject: **INFORMATION:** Alternative Method of Compliance for Airworthiness Directive AD 2008-13-17

The Wichita Aircraft Certification Office (ACO) has evaluated the installation of Williams Air Parts, Inc. Circuit Breaker Switch, Part Number (P/N) WAPI-1000X-XX as an Alternative Method of Compliance (AMOC) for Airworthiness Directive (AD) 2008-13-17. We approve the installation of the WAPI-1000X-XX series Circuit Breaker Switches, approved by Parts Manufacturer Approval No. PO4069CE, dated July 24, 2009, as an AMOC to the requirements of AD 2008-13-17. The approved Hawker Beechcraft replacement part numbers, and the equivalent AMOC Williams Air Parts replacement part numbers are identified in Table 1 below.

Original Part Number	Hawker Beechcraft Replacement Part Number	AMOC Williams Air Parts Replacement Part Number
35-380132-1	35-380132-61	WAPI-10004-5YEL
35-380132-3	35-380132-63	WAPI-10005-10YEL
35-380132-5	35-380132-65	WAPI-10006-15YEL
35-380132-7	35-380132-67	WAPI-10007-20YEL
35-380132-9	35-380132-69	WAPI-10008-30YEL
35-380132-11	35-380132-71	WAPI-10004-5BLU
35-380132-13	35-380132-73	WAPI-10005-10BLU
35-380132-15	35-380132-75	WAPI-10006-15BLU
35-380132-17	35-380132-77	WAPI-10007-20BLU
35-380132-19	35-380132-79	WAPI-10008-30BLU
35-380132-21	35-380132-81	WAPI-10004-5GRN
35-380132-23	35-380132-83	WAPI-10005-10GRN
35-380132-25	35-380132-85	WAPI-10006-15GRN
35-380132-27	35-380132-87	WAPI-10007-20GRN
35-380132-29	35-380132-89	WAPI-10008-30GRN
35-380132-31	35-380132-91	WAPI-10004-5BLK
35-380132-33	35-380132-93	WAPI-10005-10BLK

35-380132-35	35-380132-95	WAPI-10006-15BLK
35-380132-37	35-380132-97	WAPI-10007-20BLK
35-380132-39	35-380132-99	WAPI-10008-30BLK
35-380132-41	35-380132-101	WAPI-10004-5SIL
35-380132-43	35-380132-103	WAPI-10005-10SIL
35-380132-45	35-380132105	WAPI-10006-15SIL
35-380132-47	35-380132-107	WAPI-10007-20SIL
35-380132-49	35-380132-109	WAPI-10008-30SIL
35-380132-51	35-380132-111	WAPI-10009-7.5SIL
35-380132-53	35-380132-113	WAPI-10009-7.5YEL

Table 1.

This AMOC is transferable.

Before using this AMOC, notify your appropriate Principal Inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

This approval is subject to the following conditions: If in the future the ACO determines that this AMOC does not provide an acceptable level of safety, the ACO may revoke or revise the terms of the AMOC following notice to the requester and a seven-day opportunity for the requestor to comment on the revocation or proposed revision.

By the authority granted to me by the Manager, Wichita ACO, I approve the installation of the Williams Air Parts replacement part numbers as an Alternative Method of Compliance for AD 2008-13-17. This AMOC is acceptable for all Hawker Beechcraft Airplane Models identified in AD 2008-13-17.

cc:

ACE-7 (Docket No. 93-CE-43-AD)